

Freedom of Information request reference number: 7094.1

Date of response: 08/02/2023

Request:

Thank you for your email and for LFB's response to the request for information.

As you will note, the request did also ask for LFB to provide all and any documents relating to the testing, inspection and/or maintenance of the hydrants carried out by LFB within the past 3 years.

I would be grateful if the relevant documents could also be provided as part of LFB's response.


Response:

Following your request for additional information, further checks have been made. Please see below for a detail of the location for the Fire Hydrant. LFB keeps records on our databases, however, for this Fire Hydrant in particular this was recorded as live/satisfactory.

When a Hydrant is live/satisfactory and has no defects, they do not appear on any reports so LFB do not hold any documents for this Hydrant. I can confirm we only report any defective hydrants and any repairs. However, included below are the records of the inspection of the Fire Hydrant.

We have dealt with your request under the Freedom of Information Act 2000. For more information about this process please see the guidance we publish about making a request on our website: https://www.london-fire.gov.uk/about-us/transparency/request-information-from-us/





Hydrant LFB ID: 27832

130 metres south west of Beaver Road o/s no.32

Date	Action	Outcome	Notes	
30/09/2015	Station Inspection	Defective - Operable	Defect = Missing tablet	
17/04/2018	Station Inspection	Defective - Inoperable	Defect = Unable to locate Unable to locate to test. Van parked on hydrant Ford Transit	
19/06/2019	Update	Defective - Inoperable	Defect = Hydrant obstructed Obstructed by cars outsid auction, told owner they need to be moved off the Hydrant	
23/01/2026	Update	Defective - Inoperable	Defect = Hydrant obstructed Obstructed by cars outsid auction, told owner they need to be moved off the Hydrant	
26/01/2023	Update	Defective - Inoperable	Defect = Hydrant obstructed Car parked on top spoke to owner of garage who said he did not know whos it was and that he makes sure not to park on it. Sprayed kerb and put up tablet. Council needs to put exclusion hatching on it.	

	30/01/2023	Update	Defective - Inoperable	Defect = Hydrant obstructed Hydrant repositioned as per Thames Water DigDat maps. Not visible on Google Street View as most likely parked over by cars in this location.
--	------------	--------	------------------------	--

Hydrant LFB ID: 27833 In footpath/ cross over entrance to 48-50							
Date	Action	Outcome	Notes				
17/04/2018	Station Inspection	Live Satisfactory					
16/08/2022	Station Inspection	Live Satisfactory					